SURVEYED BY _____ DATE 2-25-76

℄ TIES FOR TRACT 8127

TIES SET BY RAUB-BEIN-FROST & ASSOC.

William J. Frost - "L.S. 3109"

△ = Set Orange County Survey Type "A" Mon. with Tack & Tag "L.S. 3109

● = Set Spike & Washer "L.S. 3109"

○ = Set Lead & Tag "L.S. 3109"

X = Chiseled Cross on Curb

SEE PAGE #2



SURVEYED BY [redacted] DATE 2-25-76

℄ TIES FOR TRACT 8127

TIES SET BY RAUB-BEIN-FROST & ASSOC.

William J. Frost - "L.S. 3109"

Δ = Set Orange County Survey Mon - Type "A", cap well with Tag "L.S 3109" set in conc

● = Set Spike & Washer "L.S. 3109"

o = Set Lead & Tag "L.S. 3109" in curb

X = Chiseled Cross on curb



SURVEY OF _____ INDEX _____ PAGE 3 OF 4

SURVEYED BY _____ DATE 2-25-76 [redacted]

℄ TIES FOR TRACT 8127

TIES SET BY RAUB-BEIN-FROST & ASSOC.

William J. Frost "L.S. 3109"

Δ = Set Orange County Survey Mon - Type "A", Cap Well with Tag "L.S. 3109" set in Conc.

● = Set Spike & Washer "L.S. 3109"

o = Set Lead & Tag "L.S. 3109" in curb

X = Chiseled Cross on Curb



F0702-13.1

SURVEYED BY _____ DATE 2-25-76

℄ TIES FOR TR 8127

TIES SET BY RAUB-BEIN-FROST & ASSOC.

William J. Frost - "L.S. 3109"

Δ = Set Orange County Survey Mon.

Set Type "A" - Cap Well with tag "L.S. 3109" set in concrete

● = Set Spike & Washer "L.S. 3109"

o = Set Lead & Tag "L.S. 3109" in curb

X = Chiseled Cross on curb